



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program July 20, 2011

Reviewed: 

Mine Name: Crystal Clear	Permit Number: S/023/0056
Operator Name: Edward Harris	Inspection Date: July 13, 2011
Inspector(s): Wayne Western	Time: 4:00 - 4:20 pm
Other Participants: none	Mine Status: Inspect

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection. The site has been abandoned since 2006 and there is no sign of recent activities.


Inspection Summary:

The site has been abandoned since 2006 and there is no sign of recent activities. There is no bond on the site.

Conclusions and Recommendations:

The Division should continue to monitor the site and consult with the BLM about taking enforcement action to have the Permittee reclaim the site.

Inspector's Signature



WHW:

cc: (OPERATOR)

Jerry Mansfield, BLM

O:\M023-Juab\S0230056-CrystalClear\inspections\Insp-0713-2011.doc

S/023/0056



Minor amounts of trash on site old barrels



Old abandoned structures